Australia – Victoria

No. 381 (T) - 2025

PORT OF MELBOURNE
JETTY SOUTH OF HOLDEN DOCK
PILE AND BEAM REMEDIATION WORKS

Date:	**24 July 2025**
Refers:	**N/A**
Details:	Port Users are advised that pile and beam remediation works, involving diving operations, will be undertaken at the jetty south of Holden Dock from **24 July 2025** until further notice**.**

Works will be conducted **Monday to Friday** from **0700 hrs to 1730 hrs** around shipping.

The following conditions will apply for **diving operations and works**:

1. When **diving operations** and / or **under wharf works** are within **50m** of a **berthed commercial vessel (SOLAS),** the vessel is to be **notified by the works contractor.**

2. **30 minutes** prior to commercial vessel (SOLAS) passing within 50 m of works **diving operations** and **under wharf works to cease**.

3. **No diving operations or hot works** will take place when **bunkering** is being conducted at **Holden Dock**.

Restrictions for passing **domestic commercial vessels** and **recreational vessels** during **works**:

- *Passing speed <5knots*
- *Minimum wake and wash*
- *Minimum passing distance of 50m*

Dive vessels will display International Code flag Alpha during diving operations.

Vessels supporting works can be contacted on **VHF Channel 12**.

Mariners are advised to navigate with additional caution in the vicinity of the jetty south of Holden Dock during works.

For further information, please email the Navigation Services department at NavigationServices@ports.vic.gov.au or contact Melbourne VTS on 9644 9700 / VHF Channel 12.

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
The requirements of section 232(2) have been taken into account.

Charts &	ENC AU5MEL01
Publications	
affected:	

| **Further notice:** | Further notice will be issued. |

<div align="right">

Andrew Hays
Harbour Master
Port Of Melbourne

</div>

NOT FOR NAVIGATIONAL USE