

Port of Geelong

No. 241(P) - 2025

Port of Geelong – Corio Channel Beacons 51 & 55 Installation

Date: 12 May 2025

Refers: Cancel NtM 192(T) - 2025

Details: Mariners are advised temporary buoys TB1 & TB2 have been removed and replaced by starboard lateral pile beacons 51 & 55. As per table below.


Removed Buoy	Replacement Beacon	Lat	Long	Light Characteristic
TB1	51	38°06.6467'S	144°22.3353'E	F.Iso.G.3 10m 5M
TB2	55	38°06.0085'S	144°22.919'E	F.Iso.G.3 10m 5M

Charts & Publications affected AUS 157
ENC AU5GEX01

Further notice: Further notice to follow



Paul Rasmussen
Deputy Harbour Master
Port of Geelong & Regional



NOT FOR NAVIGATIONAL USE

Victorian Notices to Mariners can be downloaded from the
Ports Victoria website www.ports.vic.gov.au