

The following Notice to Mariners is published for general information.

Victorian NTM 275(T) -2023 Western Port


Fairway Buoy Unlit

Effective 04<sup>th</sup> July 2023 .

Details: Mariners are advised that the Fairway Buoy in the Western Channel in position S 38° 30.21' ; E 145° 05.36' is temporarily unlit

Chart Affected: AUS 151

Further Notice: Further notice will be issued.



Capt. Martin Leavold

Deputy Harbour Master

Port of Hastings